

### [SELECT]

- Enter sub modes
- >2 sec. = enter setup
- Setup: move

### [MODE]

- TIME → ALTI →  
BARO → COMP → HRM
- Return to main mode
- Accept and exit setup
- >2 sec. = light



### [-BUTTON]

- Quick view of logbook
- Setup: Decrease (-)
- Scroll logbook & memory information

### [+BUTTON]


- In TIME mode Date → Seconds
- Start / Stop
- Setup: Increase (+)
- Scroll logbook & memory information

# SUUNTO ADVIZOR

## POCKET GUIDE



  
SUUNTO  
[www.suunto.com](http://www.suunto.com)



## HOW TO DO

### SET REFERENCE ALTITUDE

① Mode = ALTI ② [SELECT] > 2sec. ③ [-] or [+] to change ④ [MODE] to return

### CALIBRATE COMPASS

① Mode = COMP ② 2 x [SELECT] ③ [SELECT] > 2sec. ④ [-] ⑤ hold level, rotate 360° ⑥ repeat 4 and 5 if text PUSH – is displayed until text dOnE emerges ⑦ 2 x [MODE] to return

### START / STOP LOGBOOK

① Mode = ALTI ② 2 x [+]